

**Government of Bihar
Cabinet Secretariat Department
(Directorate of Civil Aviation)
Patna Airport, Patna-800014.**

Letter.No: CBN(Misc.) -11/2017- 370

Patna, Dated 20/12/17

Tender Notice

Sealed tenders are invited from DGCA approved organization/Company/Firms having adequate experience for the following works of Bihar Govt. King Air C-90 A/B Aircraft VT-EBG S/N 1752 :-

The details of work:-

A. Removal, overhaul of following components with required spares and installation.

Sl.No	Description	P/N	Qty.
(i)	Main landing Gear assy (LH)	90-810039-1	01
(ii)	Main landing Gear assy (RH)	90-810039-2	01
(iii)	Nose landing Gear assy	101-820029-31	01
(iv)	Propeller assy (LH)	HC-E4N-3N/E4N00131-11.SL No. HH4554	01
(v)	Propeller assy (RH)	HC-E4N-3N/E4N00131-11. SL No. HH4579	01

B. Procurement of following spares and their installation on Aircraft :-


Sl. No. 01 to 10 (List attached).

C. S/N. 11,12,13, & 14 spares will be provided by Govt. of Bihar. (List attached) and required to be installed on aircraft.


D. Re-charging of O2 Bottle of aircraft.

Terms and Condition

1. Tender must reach to the Director-cum-Spl. Secretary civil aviation directorate, Patna airport, Patna-14 on or before 15th Jan/2018 at 1700 Hrs.
2. Bidders shall submit their offer in two separate envelopes labeled as Technical Bid and Financial Bid. These two Bids shall be kept in another big envelope which should be sealed and described "Tender for overhaul and replacement of components of King Air C-90 A/B, S/n-1752 Aircraft".
3. Technical Bid should contain work experience of organization/Company/Firms (Overhaul of Hartzell propeller and Landing Gear) for min 10 Yrs.
4. Income tax return of previous year and proof of annual turnover along with audited financial statement of last three years should be submitted along with Technical bid.



5. Company should submit a certificate that the company has not been black listed by any organization/Govt. sector or Public sector unit.
6. Bank draft of Rs 50,000/- as security money payable to Director –cum chief pilot, Directorate of civil aviation, Govt. of Bihar.
7. Financial bid should contain total charges including spares required for completion of all the explained works.
8. Financial bid will be opened only of those tenderer whose technical bid will be found in order.
9. Security money of unsuccessful bidders will be refunded immediately after final selection.
10. Work should be completed within 20 days after positioning the aircraft at the decided sight.
11. Technical bid will be opened at 1500Hrs on 16th Jan 2018.
12. Financial bids of technically qualified bidders will be opened on 17th Jan 2018 at 1530 Hrs.
13. Tender will be open before the committee headed by Principal Secretary, Cabinet Secretariat Department, Bihar, Patna at his official chamber or by Departmental Purchase Committee so authorized by him before bidders/authorized representatives
14. The successful Tenderer will have to sign an agreement as per rule, any violation of agreement will be deemed as breach of contract and accordingly legal action will be taken.
15. If the contractor fails to provide the service within the contract period a penalty @1% of the total Overhaul/replacement charges will be deducted per day.
16. In case of any dispute the matter will be decided in the judicature of High court, Patna.
17. The principal secretary cabinet secretariat Department, Govt. Bihar reserves the right to reject/cancel any/all tenders without assigning any reason thereof.
18. The further details of the tender can be seen on the departmental website www.csd.bih.nic.in



Director-cum-Spl. Secretary

SECTION -A

Sl. No.	Approved TBO	Description	Part No.	Due date	Remarks
1.	Main Landing Gear Assy. LH side	Overhaul or Replace	90-810039-1	01-02-2018	Along with O/H Kit
2.	Main Landing Gear Assy. RH side	Overhaul or Replace	90-810039-2	01-02-2018	Along with O/H Kit
3.	Nose Landing Gear Assy.	Overhaul or Replace	101-820029-31	01-02-2018	Along with O/H Kit
4.	Propeller Assy. LH	Overhaul or Replace	HC-E4N-3N/E4N00131-11. SL No. HH4554	02-05-2018	Along with O/H Kit
5	Propeller Assy. RH	Overhaul or Replace	HC-E4N-3N/E4N00131-11. SL No. HH4579	02-05-2018	Along with O/H Kit

SECTION B

Sl. No.	Approved TBO	Description	Part No.	Quaintly
1	Landing gear hydraulic system filter and o ring	Replace	AN6235-3A (Filter)	01
2	Landing gear hydraulic system filter and o ring	Replace	MS 28778-6 (Oring)	01
3	Landing gear hydraulic system filter and o ring	Replace	MS28775-018(Oring)	01
4	Hose assy. LH	Replace	101-388015-3	01
5	Hose assy. RH	Replace	101-388015-7	01
6	Hose assy. LH	Replace	101-388015-1	01
7	Hose assy. RH	Replace	101-388015-5	01
8	Hose assy. RH	Replace	101-388016-13	01
9	Hose assy. RH	Replace	101-388016-13	01
10	Packing	Replace	MS28778-4	06

Baner

M. R. R. R.

SECTION C

11	Hose assy. RH	Replace	101-388016-9	01 (Available in stock)
12	Hose assy. RH	Replace	101-388016-1	01 (Available in stock)
13	Hose assy. RH	Replace	101-388016-3	01 (Available in stock)
14	wind shield	To carry out replacement of wind shield	PT NO/ 101-384025-24	(Available in stock)

SECTION D

15	Recharge the oxygen bottle in Aircraft	----	-----	-----
----	--	------	-------	-------

M.K. Pandey
14-12-17
M.K.PANDEY
QM

Basudev Hota
BASUDEV HOTA 14.12.17
CAM