Bihar Flying Institute

(Directorate of Civil Aviation) Cabinet Secretariat Department Government of Bihar Patna Airport, Patna - 800014.

Letter No: BFI Actt.02/2018 - 487

Patna, Dated : 30/1/__2018

Tender Notice

Sealed tenders are hereby invited from DGCA approved companies/firms/manufacturer/public enterprises/contractors for repair and restoration of C of A and ARC of accidental Duchess 76 aircraft (VT-EJR) including all Spare parts, accessories required during restoration of C of A, Overhaul of engines and their installation, overhaul or replacement of accessories, Radio works as called for during C of A and its restoration. All works will have to be performed at Patna base

- 1. Pre bid meeting will be held on 19.12.2018 at 03:00 PM in the office of the Principal Secretary, Cabinet Secretariat Department or authorized place by the Principal Secretary. Where a presentation will be given by the bidder regarding the said work.
- 2. The tender must reach the Chief Flight Instructor, Bihar Flying Institute, Patna Airport on or before 28/12/2018 by speed post or registered post by 5:00 P.M.
- 3. Bidders shall submit their offer in two separate sealed envelopes labeled as Technical Bid and Financial bid. These two bids shall be kept in another big envelop which will be sealed and be subscribed "Tender for Repair Works, Radio Work and restoration of C of A of "Duchess 76 Aircraft".
- Technical Bid should contain the following :
 - a. The company/firm/public/contractors should have experience for working on Duchess-76 /multi engine aircrafts. They are also required to submit qualifications and experience details of Engineers and Technicial staff who will be engaged in the repair works.
 - b. Service condition of engineers and Technicial staff i.e. whether they are on regular pay roll or on contract basis. If on contract, the period of contract should be clearly indicated in writing with NOC.
 - c. A Bank Draft / Banker's Cheque amounting Rs 50,000/-(Fifty Thousand) only as security money payable to Director-Cum-Chief Pilot, Directorate of Civil Aviation, Govt. of Bihar, Patna has to be submitted by the Bidders. Security money of disqualified bidders will be refunded immediately after final selection.
 - d. Financial bid should contain the quoted rate for repairing works for the aircraft inclusive of boarding, lodging & transportation charges of engineers and Technicial staff. The bidders are also required to mention separately other charges i.e. tax payable. Quoted rate should be valid till 28/12/2019. Financial bid will be opened only of those bidders whose technical bid will be found in order.
- 5. Technical and Financial bid of the tender will be opened on 03/01/2019 and 04/01/2019 respectively at 3:00 P.M. before the committee headed by Principal Secretary, Cabinet Secretariat Department, Bihar, Patna or by an officer so authorized by him before representatives of Companies/Firms and Public enterprises.
- 6. The successful bidder will have to do all other subsidiary works which will come across in the course of doing the aforesaid work for which no extra charges will be given. The hangar space and available serviceable tools will be made available to the company. In case any other special tool is required that will have to be procured by the company for which no extra payment will be given.
- 7. The successful bidder will have to sign an agreement as per rules.
- 8. The successful bidder will have to obtain approval of Patna base within the 15 days from the date of award of contract.
- 9. In case of any dispute, the place of settlement will be within the judicature of High court, Patna.
- 10. The principal Secretary/Secretary, Cabinet Secretariat Department, Bihar reserves the right to reject/ cancel any/all tenders without assigning any reason thereof.
- 11. The additional information of tender can also be seen on this Department's website www.csd.bih.nic.in . The bidder should contact this department on our email sheo.prakash10@gmail.com and mob. No. 9431651514.

(Chief Flight Instructor)



Spare Parts of Duchess-76 Aircraft as per the following:-

		Nomenclature	Quantity	
SI.no	Part Number	Spring Nose Gear extension	02	
_1	100942AF0405-92	Selector Valve	01	
2.	105-389010-1	Hose Assembly	102 '	
3	3300907F6-0120	Tyre 6 Ply tube type	04	
<u>4.</u>	R 1750x600-6	Tube Assembly	04	
5	R 1750x600-6	Hose	02	
6	1062008-12-48	·	0.5	
<u>7. </u>	106200162-80	Hose	02	
8	106200162-40	Skin AFT Floor	01	
9	169-420028-213	• · · · · · · · · · · · · · · · · · · ·	02	
10.	106200G12-48	Tube	02	
11.	105-320011-7	Tube	02	
12.	131152-9A14		02	
13.	130936PA0360	Tube	02	
<u> 14.</u>	130936PA0160	Tube	02	
15.	130936912A0240	Tube	02	
1 <u>6</u>	130936P10A0210	Tube	01	
17	1131152-9A32	Tube	03	
18.	130936P10A0050	Tube	02	
19.	130936P10A0060	Tube	01	
20.	13093610A0030	Tube	01	
21.	105-320011-9	Tube	81	
22.	130936P10A0280	Tube	01	
23.	169-580001-25	Tube	102	
24.	169-5800014-281	Tube	01	
5.	130-936P4A	Tube	101	
26.	106-242-6-00800	Tube	192	
27.	105-320021-15	Tube	01	
28.	LW-161171	Support Assembly	01	
29.	105-420000-86	Skin Fuselage cabin Bottom Centre RH	01	
30.	105-420000-165	Skin Fuselage cabin Bottom Centre LH		
31.	105-400005-288	Skin Fuselage cabin Bottom Centre RH	101	
32.	169-420028-163	Skin Fuselage Cabin AFT LH	1 01	
33.	169-400005-290	Skin Fuselage Cabin AFT RH	06	
34.	PRP-9-6	O-ring	01	
35.	105-410000-82	Door Assy. Nose gear RH	$-\frac{101}{01}$	
36.	105-774CZE4305	Pin hinge		
	2-10	Fire Extinguisher	01	
37.		Hose	02	
<u>38.</u>	130524-3-124	Bolt	02	
<u> 39. </u>	130-909-B-14		12	
40.	RPR909-1	O- ring	101	
41.	169-810032-24	Housing LH	01	
42.	169-810032-23	Housing RH	02	
43.	MS28775-15	O-ring Outer Seal	02	
44.	MS28775-8	O-ring Inner Seal	02	
45.	MS193471-12C016	Sleeve lower		
46.	MS193471-10C024	Sleeve upper	02	

fin

s.		Wiper ring	02
47.	MS11065-29-1	Hose Assy. Manifold	02
48.	130524-3-0260	Pressure	l l <u>'</u>
40.		Hose	02
49.	1062006-4		02
49. – – – – – – – – – – – – – – – – – – –	106-910003-3	Hose Duct Air intake	01
	111716AY6XX55-1		01
51.	169-380100-1	Hose Assy.	02
<u>52.</u>	40C200 C-12-80	Hose	04
53.	54000 9 c c-111-41/-450004	Hose	02
54.	1 20 C 24 2 0 260 S S-11 [41/23 0 200	Hose	Q 2
55.	33099F8-0130S s.s-111F417-8D0130	Hose	01
56.	130907CA8098	Duct	01
57	130907CAC140	Duct	01
58	130907CAC140	Duct	01
59	11716AZ6XX21	Actuator Assy. Rudder	
60.	169524085-5	Tab	01
	121/	Hose Assy	101
61	153-64002-121/2	Hose Assy	-
62	153-64002-8	Hose Assy	1 01 02
63.	153-64002-26	Hose Assy	
64.	153-64002-8	Hose Assy	02
65.	153-64002-07000	Belt	02
66.	169-534108-11	Harness Assy.	02
67.	5009779-12	Restrain installation	02
68.	169-534107-15	Passenger	
55.		Exhaust Assy.	102
69.	8295-100	Antenna NAV	01
70.	C1-158-C/2	Antenna ADF	01
71.	KA-44B	Antenna Transponder	91
72.	KA-80	Accumulator-Prop	02
73.	8907-021		
, ,,		Governor Strap lower fuselage	02
74.	R1054240139	inboard	
, 7.		Strap lower fuselage	02
75.	105-4240-141		
75.	100 12 10 2 1	outboard	01.
	105-42000-117	Stringer LH	01
76.	105-42000-115	Stringer LH	
<u>77.</u>	105-42000-15	Channel LH	01
78.	105-420000-13	Channel	

